

# Site work today

v01: dropped EC100 box, reprogrammed to 20sps/10Hz filter, reinstalled box

v07: had to pio to get Li7500 running again. Upper DSM probably needs ground strap. Li7500 box probably needs ground strap.

v06: added ground strap to DSM. Li7500 box probably needs ground strap, though it was still running from this morning's reset.

tnw05: reseated Tsoil connectors multiple times. Still reports 0.001 for all probes. Will replace (stealing from tse05, that probably won't be erected).