

a8 TRH restarted

A8 upper TRH needed a eio 5 0/1 to restart.