

TRH.0.5m.A10 died

Within 2 seconds of me turning off cockpit for the night last night, this sensor died. The DIN connector had pulled out in the mote box. Fixed about 7:20 this morning (15 Nov).