

## Rad wetness moved to soil.a2

12:00 -12:15: Due to the loss of a port on the RAD mote, the wetness sensor was moved to a port on the soil.a2 mote. The sensor remained on the darkhorse.