

20m IRT removed

July 13, 2013

~10:30am CDT

Removed IRT from mote due to crashing the mote. Once sensor was down, noticed the back-shell of sensor (PVC part) was full of water. FULL.

Will replace with a dry IRT.