

20m IRT outage

20m Tsfc out from ~ 12July 2:00 - 14July 9:30

The old sensor filled with water apparently from the back/bulgin side.

The new sensor installed 7/14 ~9:30 but not seen in cockpit or covars. Looking directly at the mote using 'mp=1' dsm-printable it is reporting. Its i2c address is 0x3c, serial number 1. The xml may be looking for a different address.