

# mote repair

10/5/13 twh

John was correct. The mote replaced at rad.flr (SN-19) did have the radio disconnected from the socket on the back of the main board. Repaired today.