

Service visit to FAR

10/11/13, twh: 4:14 - 4:20 pm

Cleaned kh2o, radiometers, wetness sensor.

Soil mote stand blown over about 45 degrees to the north. This stretched the soil sensor wires. Did it disturb the sensors?. Mote stand needs a third stake on the south.