

Service visit to RIM

10/12, twh

Gordon and I visited the RIM station to measure guy wire tensions, add strap to hold the door closed to the upper mote, and to replace the 20m TRH.

The TRH was fixed by removing jumpers unnecessarily providing power to the power monitors. See related blog post.