

BAO site visit

replaced trh at 11:00 AM local time,

checked to make sure leaf wetness sensor is installed properly, (it was), and took site photos

BAO flux site photos





