

NR01 status

The short wave incoming signal from mote #1 is bad. I expect this is a loose connection to the PIC.

The sensor will need to be brought back to the base for repairs.

Since we have 2 other NR01s at this site I do not see the need to immediately fix it unless we decide to move it and mote #4 to other sites that are more favorable to soil installation.