

# Visit rsw02

Added a second DSM to this site to sample all but the analog Setra sensor. Fixed noisy messages from 10m RMYoung by moving it to a different port. RMYoung at 20m is reporting non-zero diagnostic flag, and nothing we did fixed it. The voltage at the DSM mote is 12.7V, but maybe there's too much of a drop up the tower, or maybe the RMYoung is beyond it's useful life.

- ☐ Replace the RMYoung at 20m.
- ☒ Rearrange the DSMs so that both have a clear view of the sky. Putting rsw02x directly above rsw02 seems to have prevented GPS lock in rsw02. Oops.

The JIRA issue on the crashing Titan problem has been updated: [ISFS-149](#).