

# april 15th setup notes

RSW 2 visit - 10 m sonic ok, 20 m sonic not good, will replace later

RSW 3 40 m TRH faulty, will replace later.

RSW 4 leaf wetness sensor - added pic processor

20 m licor RTS/DTS? no jumpers in Viper box to address.

RSW.in - RSW.out - config change? not sure how to accommodate.

RSW 5 added POE cable (ops center made for Ubiquity Ant, now have telecoms but realized that was not needed because sonic port and Ubiquity ports were switched.

sentra pwr was not plugged in.

now all is O.K.