

# TRH Swaps - Issue at Mars

3June06 ~10:15MDT

4m TRH swapped because it'd been bad (See GM's note) sn-out=13 sn-in=008 It was generating continuous spurious interrupts. Only the michro-chip 'wand' was replaced, not the shield.

6m TRH removed s/n15 because of bad 'shield' (dc-dc, sio, etc). Swapped 2m TRH up to 6m to avoid climbing later: sn10 is now at 6m

	Level	TRH S/N	Notes
2		Will be replaced later today.....	
4	8	Installed today	
6	10	Swapped in from 2m today	
8	5		
10	14		