Sensor outages

Just to record this:

- Since 28 Aug, the wetness sensor has read "0" about half the time. I suspect a cable issue.
 Since 28 July(!), all Tsoils have started reading negative 273 from time to time. Now a month later, almost no readings are good. Is this a lightning-related failure of the reference resistor?