

site playa1 visit

12 Jan 2011 1600-1630 on site John and Ling

1605 installed insulation and added a third battery. One of battery terminal lugs was loose when we arrived. That may have had some effect on charging but minimal if any. The TRH fan definitely 'noticed' the voltage swings as we paralleled in a 3rd battery onto the one that had the loose terminal.

Notes:

1> TRH fan is noisy and may need to be replaced. It did sound more steady after adding the 3rd battery.

2> 2 Batteries' caps were/are missing.