

River7 site visit, jan 23

23 Jan: Oncley&Militzer

Conditions: just a bit of snow clumped on the curb

1210: adjusted SPN-1 level (off by about a bubble -- the soil post is leaning)

1213: dry wiped radiometers

Until 1225: messed with shadowband adjustment. Shifted the azimuth a bit to point nearly S, adjusted elevation to 60 deg (from 53), adjusted sensor level, moved collar to center shadow.