

krypton 1390 needs work

Based on the tests just performed at ncar4, it appears that there is a loose connection on the cables from the krypton head on S/N 1390. I would suggest rebuilding these connectors (the SMC and the MS) prior to a future deployment.