upwind rebuilt

upwind now has the Viper board from spare and has just been restarted. Also the Ethernet cable was changed to a different port on the hub located in downwind2. We'll see whether it stays up tonight!