2 data notes

1. Yesterday afternoon, the ue GPS started looking good again. Maybe it didn't like one of Ethan's SD cards!
2. Vtherm from the Apogees has had occasional large spikes. I'm assuming this is our same popsicle stick firmware issue (for which we now have a fix). We can remove these spikes in our software with "maxValue". I'll try to get this implemented.