

Pressure 11B back on line

The interface board being used for 11B had a bad RJ45 connector. This was fixed and the board was installed at Pressure2. PARO 11B was attached and data looks good. This occurred around 10:00am local.