

Leak found in Pressure line

A variety of pressure tests were conducted on the pressure lines. Th first was a check of the reference cell. There appeared to be a very slow leak. The main line was tested a major leak was found. It was at the end of the line where a tee was instead of a straight coupler. This was fixed around 2:30 pm.; We will see what happens over the next few hours.