

upwind power

Gordon suggested that the problems with upwind might be due to power. Measuring at the power frontpanel (both inside and outside the box) I see 12.93 V, which I would say is fine. We need another explanation...