

Replaced Mote 12 with Mote 8 at rsw04

Mote 12 was the one that stopped working when initially installed at rsw02, but it got installed on the radiation stand at rsw04 to cap the soil sensor cables. I installed mote 8 in its place to bring it back to EOL for testing.

No progress on the rsw04 tower. The tower sections are still laying on the ground.