

## tse07 woes

10m CSAT is in constant reset mode since midday yesterday. TP01 completely died at the same time. Just visited and found a liter of water in the battery cooler (can you say "VERTEX"?). Powered station down, dumped water out, cleaned up a bit, and restarted station, but no change in sensor status. Guess we have to go back prepared with spares.