

tse07 work

The 10m sonic here fixed itself overnight. I'm mystified as to why the CSATs do this – not finding a signal to trigger on for hours at a time, but I'm not complaining much.

The TP01 also died 2 days ago. Turned out to be a cold solder joint on the higher-current resettable fuse we had installed on the motes. Replaced this fuse and now is working.