

East end transformer odd

While Larry and I were working on C tonight, we noticed that the transformer was "mooing" about every 5 seconds. I had the impression that it was choosing a different tap every time (Bill's?) SODAR beeped. It didn't sound normal or healthy.