

# Soil.g down, restarted

14-Oct-12 ~10:50MDT, 16:50Z

Soil.G down ~18:30Z 10/13 until ~16:50Z 10/14.

Based on qc plots the mote died, perhaps due to one of the several rain showers yesterday, but that's uncertain. Upon visual examination the mote was operating properly (ie 1-sec clock and 5-sec polling/send). It may be possible that the blue-tooth antenna connector came loose because when swapping in a new mote, it was off (or that happened when i jiggled things). Anyway, I swapped to test console and it started up correctly: everything good. When trying the spare mote, sn4 which was here and bad previously, it did not work despite having new software reinstalled. I ended up putting it back together with what works: the prototype V2 mote as it had been.