

Aph3 0.5m TRH troubles

Noticed the 0.5m TRH at station 3 was not reporting. If I try to recycle power on port, nothing happens. If I recycle power on station it works for a few seconds. So I went out to station 3 and decided to replace the TRH probe. Rebooted system and awaiting results.

Removed probe 024 and put in probe 048. Funny.