

## 20m Licor Fixed

Found the problem with the 20m licor was the serial cable from electronics to dsm. Bulgin connector at dsm was full of water. Ran a new serial line from Licor to dsm. All is good!