

Tsoil.b

Overnight, Tsoil.b died. By playing around at about 1030-1045 today, we've determined that the probe itself is now not working. (Though we did see some evidence of water in the mote box.) We'll install a spare later today.