

wetness now on mote 18 (a2)

Since we think that one of the ports on Mote 11 is dead, at about 1215 we moved the wetness sensor to Mote 18 that was installed yesterday. I've added the new mote ID to its configuration.