

# Secured pond tipping bucket

We had noticed that the tipping bucket mount was somewhat shaky. I have just secured it by a bit of guying. The bubble level had been out of the outer ring and now is within the inner ring (though not exactly centered).