

8KVA fuse blown

11:30 - 13:50: The 8KVA blew its fuse so Steve and I decide to remove the surge suppression black box. It turned into a bigger deal since we had to remove a side panel that had some rivets. To add to the fun, while going out to the site the car decided to place a small rock between the brake pad and a pad cover which resulted in a horrible noise. So one of us played mechanic and the other electrician.