Rad cleaning

Forgot to log that this morning at about 0900 I cleaned all the under-canopy radiometers. I did the wetness drop trick to note the time.

At this time, I also added a PAR sensor at 2m, though it isn't really mounted and not exactly in a good spot.