

Etherant status

Due to the wireless outages we decided to move the .14 network to the AP24 internal antenna. This took place over the course of today. Since the mast had to be lowered, wires run, changes to the AP24 firmware, etc. As a result the SNR from downwind2 and profile has almost doubled. The tx-power on the internal was set to 25, gain to 0.

A backup configuration for the previous configuration and the new one were created. They can be found in the AP24 directory file.

Alico-11072008-2300.backup (old)

Alico-12072008-2252.backup (new)

network address for AP24:

internal: 192.168.14..251

external 192.168.12.251