

4m TRH changed on profile

The 4m TRH, on profile, was replaced this morning. The RH of sensor 8 was ready a little low compared to the other TRHs. Sensor 8 was replaced with sensor 10.

UPDATE: It appears the protective cover was left on the sensor. The humidity is ready too high! It was removed at about 14:00. However, the RH from this position is still a bit low!