

Upwind status

After the 10:30 pm event, Upwind kept running throughout the night. Gordon had a chance to look at the log messages and thinks the problem may be with the seating of the micro-drive on the Viper board. The micro-drive was re-seated this morning.