

replaced 8m profile sonic

Since the winds (u-component) have seemed to be about 0.3m/s low (since the beginning of this experiment), we replaced it (~0830-0930 this morning). We removed S/N 733 and installed S/N 369.