

FLR radiation mote

10/4/13, twh

The radiation mote at FLR was not reporting. It looked like it was sampling the data okay, but John suggested that the radio might have shaken loose from where it plugs into the main mote board. I replaced the mote and it began reporting data okay. I removed the GPS jumper and brought the original mote back to the base for inspection.

Gordon reported that the SPN1 mote was not sending data. It appeared to be hung with a solid yellow light in the middle of the board. I recycled power and that appeared to fix it.

Sebastian cleaned the radiometers and noticed the some require new dessicant. Something to check for all the radiometers.