

# Service visit to NEAR

Tom, Gordon arrived 2:45 local

Replaced trh transducer at 25m, due to anomalously high RH. Transducer was #43. Replaced with #25.

Checked base mote. Antenna cable connection inside white box was a bit loose, was able to tighten 3/4 turn by fingers.

Plugged ethernet cable from nearup into surge protector inside near DSM. It was going straight into the switch box.

Removed GPS jumper on soil mote. All antennas tight on motes.

Raised rad stand to 2.02 meters. Pyranometer bubble is in the circle. Pyrgeometer bubble high to south.

Left rad stand at 4:02. Departed site at 4:06