

Service visits to NEAR

10/12/13

14:10 Visited NEAR to measure guy wire tensions and remove power jumpers on serial ports for power motes.

16:50 Tested FAR pyrgeometer by plugging into radiation mote. Worked okay.