

Near mote work

At about 1230, removed near soil mote since we had seen intermittent data transmissions and I noted visually that the XBee radio was not completely seated on the mote board. Brought it back to the trailer and fixed. Replaced at about 14:20?