

## **P.sw.flr back up**

10:20 - P.sw.flr is running again. Steve O. and Steve C. replaced the battery. Old voltage was down to 4.4V. New read upwards of 15V.