

# TRH work from yesterday

Site 11: TRH26 was replaced with TRH29

Site 5: The TRH shield was replaced due to flaky Ifan values

Results: Both sites looking good