

EC150 probably wet

As of about 1500 today, the EC150 h₂o and co₂ channels have stopped reporting. No doubt they are offscale with lots of water on the lenses. Hopefully, both will come back when the rain stops.

P.S. Now that the rain has stopped for a while, both signals are back, though both higher than they should be – likely still with water on them. We'll look again in the morning.