

S5 TRH fan stopped

This was the TRH that we just swapped in yesterday to avoid fan issues in the previous sensor! Fan was turned off by the PIC, presumably because Ifan exceeded the 80mA threshold. Control-R brought it back. Now reading ~28mA, which is a bit low, if anything. Strange... What could it be about this station that it kills TRHs??