

Second trip at high tide

Measured azimuth angles at site 10 and site 12

Swapped out T/RH at site 13 at 5:00pm EDT. (Didn't notice until replacement was complete that previous T/RH seems to have recovered around noon today).

TRH response was surprisingly slow. The inlet of the replacement was probably warmed by being hand carried.

