

Status up to 2017-06-14

No changes in instruments, everything seems to have been working as usual for the last few days.

I had to cycle the power on rsw02 twice in the last 24 hours, after it got hung up and stopped responding to pings, so we lost a few hours of data for P.2m. rsw02.

The substitute Ubiquiti radio at tnw05 eventually stopped working for some reason. When I visited the site on Sunday to fix it, it came back after cycling the power. Then it went out again by the next day. So I visited the site again on Monday and swapped the original radio back into operation. Since then that radio has not had any problems. Go figure.

I leave today, Kurt and Dan are on their way here with another truck.