Status - Mar 20

- s1: not reporting. Last message (18 Mar) missing P, Vbatt was okay.
- s3: all working
- s4: all working
- s8: ec150 not installed
- s10: all working
- s14: P, TRH, mote all down (mote has a lot of 0x00 characters before message)
- s15: Qsoil needed power cycle
- s17: not reporting, suspect DSM usb issue. Last message (13 Mar) had bad TRH fan, RH questionable, missing Ott, missing TP01 (might just have been timing, since prior message was okay), Vbatt was okay